




Photograph 25. Vegetation along disturbed area of Lalor Access Road (6 July 2010)



Photograph 26. Drill road to north of cleared alignment (6 July 2010)



Photograph 27. Disturbed area to north of Lalor Access Road alignment (6 July 2010)



Photograph 28. Vegetation downstream of culvert crossing 1 (Lalor Access Road) (6 July 2010)



Photograph 29. Vegetation upstream of culvert crossing 1 (Lalor Access Road) (6 July 2010)



Photograph 30. Vegetation downstream of culvert crossing 1 (Lalor Access Road) (6 July 2010)



Photograph 31. Culvert crossing 1 (Lalor Access Road) (6 July 2010)



Photograph 32. The Lalor site (1 June 2011)



Photograph 33. Lalor site in wet bog off the rock outcrop. (1 June 2011)



Photograph 34. Margin of the rock outcrop and the Lalor site. (1 June 2011)



Photograph 35. Dense Black Spruce bog surrounding the Lalor site. (1 June 2011)



Photograph 36. Wet bog area adjoining the Lalor Access Road. (1 June 2011)



Photograph 37. Vent shaft and Lalor Access Road. (1 June 2011)



Photograph 38. Water pipelines adjacent to Lalor Access Road. (1 June 2011)



Photograph 39. General area of former rail bed. (1 June 2011)



Photograph 40. Rock cuts along the former rail bed. (1 June 2011)



Photograph 41. Former Anderson Mine site with Anderson TIA in background. (1 June 2011)



Photograph 42. Beaver pond adjacent to former rail bed. (1 June 2011)



Photograph 43. Beaver pond just east of the existing PR 392 crossing. (31 May 2011)



Photograph 44. Black Spruce stand on the north side of Anderson Creek. (31 May 2011)



Photograph 45. Deciduous inclusions on the north side of Anderson Creek. (31 May 2011)



Photograph 46. Open Black Spruce stand on the south side of Anderson Creek. (31 May 2011)



Photograph 47. Fairy Slipper Orchid Observed along PR 395, south of the Lalor Access Road (*Calypso bulbosa*). (12 June 2012)